


BUILDING SAFETY CERTIFICATE

Certified that the existing building Orchids The International School, Survey no. 123, Vidya Vally School Road, Near Teerth Aarohi, Parkhe Vasti, Sus, Taluka-Mulshi, Dist-Pune. is having block (s) / Floor(s) as per details below.

Detail Block(s) in School	block (1)
No. of Floor(s) in the Block	Ground Floor + Upper Floor 5 Floor.

The building is owned/occupied by Orchids The International School, Survey no. 123, Vidya Vally School Road, Near Teerth Aarohi, Parkhe Vasti, Sus, Taluka-Mulshi, Dist-Pune. have complied with the Building safety requirements and verified by the officers concerned of Public Works Department Pune on 15/09/2026 in the presence of, Ms. Priyanka Nathwale, Principal, Orchids The International School, Survey no. 123, Vidya Vally School Road, Near Teerth Aarohi, Parkhe Vasti, Sus, Taluka-Mulshi, Dist-Pune. and that the building is fit for occupancy for running school with effect from 15/09/2026 for a period of One year


Issued on 29/09/2026 at Pune by


(S.A. Kotkar)

Sub Divisional Engineer,
P. W. Sub Division No.5
Pune-411011.



'Countersigned'




(Prashant S. Khairmode)


Executive Engineer,
Pune Public Works Division,
Pune-411001.

OW.No./ DB / NOC / 6661/2026
Office of the Executive Engineer,
Pune Public Works Division, Pune-01.
Date :- 29 SEP 2026

Copy to :- 1 Orchids The International School, Survey no. 123, Vidya Vally School Road, Near Teerth Aarohi, Parkhe Vasti, Sus, Taluka-Mulshi, Dist-Pune.
2. Sub Divisional Engineer, P. W. Sub Division No.5, Pune 411001.



School Manager
ORCHIDS THE INTERNATIONAL SCHOOL
Survey No.123, Vidya Valley School Road,
Near Teerth Aarohi, Parkhe Vasti, Sus-411021.



Principal
ORCHIDS THE INTERNATIONAL SCHOOL
Survey No.123, Vidya Valley School Road,
Near Teerth Aarohi, Parkhe Vasti, Sus-411021.